# **MicroStrain by HBK Technical Note**

## 3DM-GV7-INS

### **Current Firmware Upgrade**

<u>Date</u>

May 16, 2024

#### Summary

This technical note details the most current firmware available for the MicroStrain by HBK model 6290-9920 **3DM-GV7-INS** inertial sensor. The technical note additionally describes firmware changes since the initial product release and the use of SensorConnect software to perform the firmware upgrade.

#### <u>Detail</u>

As we see in the table below, the current firmware is version **1.2.03**. This firmware is contained in the file object entitled **cv7\_gv7\_ins\_firmware\_v1203\_b16.zhex**.

#### 3DM-GV7-INS Firmware

Firmware	ChangeLog
Version	
1.2.03	Initial Firmware Release

#### Upgrading Firmware With SensorConnect

The firmware on the **3DM-GV7-INS** inertial sensor may be upgraded with MicroStrain by HBK's SensorConnect software. This Windows software is available for download and installation on the MicroStrain by HBK website at: <u>https://www.microstrain.com/software/sensorconnect</u>. The user is required to download the ZHEX file from the **3DM-GV7-INS** web page. SensorConnect performs the upgrade under user control.

#### **Support**

MicroStrain by HBK support engineers are always available by phone, email, chat, and Teams to support you in any way we can.



MicroStrain by HBK Hottinger Brüel & Kjær 459 Hurricane Lane Williston, VT 05495 • USA phone: +1.802.862.6629 email: microstrainsales@hbkworld.com microstrainsupport@hbkworld.com www.microstrain.com www.hbkworld.com